



End of project impact report

Organisation Details

Name: CRIDLING STUBBS VILLAGE HALL

Address: WRIGHTS LANE
CRIDLING STUBBS
NORTH YORKSHIRE.

Postcode: WF 11 0AS

Project Details

Description: BUILDING CONDITION SURVEY.

Contact Name: COLIN BEDDOW Tel: _____

IMPACT REPORT FOR PERIOD OCTOBER 2017 TO DECEMBER 2017



Q1 In no more than 500 words please outline the key outcomes of your project.

The ~~report~~ project has produced a fair & factual report of the building condition. It confirms that the contractor appointed by the previous management committee to repair the porch roof and kitchen roof did not have the skill or resources to carry out the work. He actually vandalised ~~the~~ building & abandoned his unsatisfactory work.

Q2 In no more than 500 words please demonstrate how the project has met the Community Development Plan objectives that were identified in the original application for funding.

The project has confirmed that ~~the~~ college hall is a sound building. The general fabric of the building is in good condition. The building is dry and is showing no signs of structural distress. A planned schedule of minor maintenance will keep the hall in good usable condition for years to come.



Q3 In no more than 250 words please give details of any additional benefits or objectives that the project has met that were not anticipated/ outlined in the original application for funding.



Any other comments on the project and its success:

A large, empty rectangular box with a thin black border, intended for providing comments on the project and its success.